

Bind Key Summary for Layout Window

	F1	F2	F3	F4	F5	F6	F7	F8	F9	F10	F11	F12	
Key alone		Save Cell	Invoke Options Form	Selection Mode	Rule-driven Mode	Snap Mode	Reset DX/DY	Clear Highlight	Show/Hide Flight Lines				Key alone
Ctrl +										Capture			Ctrl +
Shift +									Show Flight Lines by Repeat Selection				Shift +
	a	b	c	d	e	f	g	h	i	j	k	l	
Key alone	Align	Up One Level	Copy	Measure Distance	View DRC Error	Zoom All	Gravity	Input Coordinates	Create Instance		Tag Ruler	Create Text	Key alone
Ctrl +	Select All	Return To Level	Stop building flight lines	Deselect All	Swap Port	Min View Level							Ctrl +
Shift +	Area Select	Return To Top	Chop	Create	View Error	Max View Level	Create Guard Ring				Clear Ruler	Last View	Shift +
	m	n	o	p	q	r	s	t	u	v	w	x	
Key alone	Move	Hierarchical Net Tracer	Create Contact	Create Path	Attribute	Create Rectangle	Stretch	Layer Tap	Undo	View Level -1	Backward View	Edit In Place	Key alone
Ctrl +	Create Transistor			Convert to Object		Redraw	Split	Auto Merge/Split Transistor				Fit To Edit	Ctrl +
Shift +	Merge	Highlight Net	Rotate	Create Polygon	Create Pin	Reshape	Find	Design Hierarchy	Redo	View Level +1	Forward View	Descend Mode	Shift +
	y	z	[]	-	+	>	. (period)	;	Esc	Tab	BackSpace	
Key alone	Yank	Area Zoom	Decrease Path Width	Increase Path Width	Change to Lower Layer	Change to Upper Layer		Repeat	Last Command	Close Options Form Abort Command	Jump to Input Text Field within the Form	Delete a point	Key alone
Ctrl +		Zoom In											Ctrl +
Shift +	Paste	Zoom Out					Attach				Pan		Shift +
Spacebar													
Key alone	Magic key for the Rule-driven, Display Ruler, DRC Pathfinder and Push-Wire Modes Toggle key for the Cycle Selection and DRC by Area Modes, and the Reshape, Boolean, Align, and Chop Commands												

Bind Key Summary for Matching Device Creator Window

	a	b	c	d	e	f	g	h	i	j	k	l	
Key alone	Add Pattern			Measure Distance		Zoom All							Key alone
Ctrl +				Deselect All		Min View Level		Re-chain Connection					Ctrl +
Shift +						Max View Level					Clear Ruler		Shift +
	m	n	o	p	q	r	s	t	u	v	w	x	
Key alone					Attribute				Undo	View Level -1	Last View		Key alone
Ctrl +						Redraw							Ctrl +
Shift +						Repeat Pattern			Redo	View Level +1			Shift +
	y	z	[]	-	+	>	;	Delete	Esc	Tab	BackSpace	
Key alone									Delete Pattern	Close Options Form Abort Command	Jump to Input Text Field within the Form		Key alone
Ctrl +		Zoom In											Ctrl +
Shift +		Zoom Out											Shift +

Bind Key Summary for Stick Diagram Compiler Window

	a	b	c	d	e	f	g	h	i	j	k	l	
Key alone	Align Gates			Measure Distance									Key alone
Ctrl +				Deselect All		Merge							Ctrl +
Shift +	Unalign All Gates		Re-chain			Fold					Clear Ruler		Shift +
	m	n	o	p	q	r	s	t	u	v	w	x	
Key alone	Move						Swap		Undo		Last View		Key alone
Ctrl +						Redraw	Split						Ctrl +
Shift +	Merge Gates								Redo				Shift +
	y	z	[]	-	+	>	;	Delete	Esc	Tab	BackSpace	
Key alone			Optimize OD						Delete Transistors	Close Options Form Abort Command	Jump to Input Text Field within the Form		Key alone
Ctrl +													Ctrl +
Shift +													Shift +